



## Advisory Notice for Titan T-51 Mustang Aircraft

March 6<sup>th</sup>, 2020

### Inspection required before any further flights

#### Affected aircraft:

- All Mustangs

#### Aircraft not affected:

- None

#### Circumstances:

**Aileron Spar cracks** near the **Aileron Driver Bracket**. Cracks were found in an aircraft with approximately 300 hours of total flight time

#### Inspection required:

Every 100 hours, during an annual, or condition inspection, inspect the Aileron Spar near the driver bracket for cracks, as shown in FIG 1 and FIG 2. This area must be inspected thoroughly. If the Surface is painted inspect carefully to be sure there are no cracks, remove paint if necessary.

#### Corrective action:

If a crack is found, the spar must be repaired or replaced before any further flights.

Contact Titan Aircraft: 440-275-3205 or email [support@titanaircraft.com](mailto:support@titanaircraft.com) with any questions or concerns.

Best Regards,

A handwritten signature in black ink that reads "John Williams".

John Williams

President

Titan Aircraft

fig.1



fig. 2

