



Advisory Notice for Titan T-51 Mustang Aircraft

March 4, 2009

Service required before attaching Center Section Skins

Affected aircraft:

- All Aircraft

Aircraft not affected:

- None

Circumstances:

A builder finished the center section without pressure checking the fuel tanks for leaks. Upon filling the tanks up with fuel, leaks were discovered. This required the removal of the skins and the fuel tanks to reseal them.

Inspection required:

There is no inspection required. This is a mandatory service for all affected aircraft.

Corrective action:

The fuel tanks should be checked for leaks prior to installing them. Each tank, with fitting installed, **must** be pressure checked with no more than 1/4 lb of air pressure. If a leak is detected at a fitting, remove and reseal it, then perform another leak test. If a leak is detected in the tank itself, Titan Aircraft will replace it.

Contact Titan Aircraft: 440-275-3205 or email support@titanaircraft.com with any questions or concern.

Best regards,

A handwritten signature in blue ink that reads "John Williams".

John Williams
President
Titan Aircraft